Inspected	Description	Measurements	Survey Notes	Condition	Recommendations
09-Apr-2017	Roadside, near bend in road. Linder large oak	Mgmt Auth: Am. CC Width (m): 1.2 Material: Wood	Getting very overgrown	Requires	needs clearance of nettles and overgrowth Timescale: Urgent
30-Jan-2016		Mgmt Auth: Am. CC Width (m): 1.2		ОК	
5-May-2013	Roadside near bend in road	Mgmt Auth: Am. CC Width (m): 1.2	Brambles an issue.	Requires Attention	needs clearance of overgrowth Timescale: Urgent
14-Jan-2010	Roadside	Mgmt Auth: land owner Width (m): 1.2	Replaced 2010.	ОК	
28-Feb-2008	Roadside	Width (m): 1.2	Installed circa. 1995		step board starting to go Timescale: 1 Year