


Details of site furniture inspections



Site name: Estate Land

Contact: Owner

Items: 6

Items requiring action: 5

Ref.	Type	Description	Measurements	Survey Notes	Overall Condition	Inspected	Inspect Period
DF34	Fence - post and rail 'pre-1980 model'	Between the two main pastures.	Height(m): Length(m): 70 Width(m): Group size: Colour: Construction: metal	ok	Not Recorded	16-Jan-12	-
DF35	Fence - post and wire	Along foot of the embankment	Height(m): Length(m): 430 Width(m): Group size: Colour: green Construction:		Good	16-Jan-12	2 Years
DF37	Fence - post and rail	Along the main road.	Height(m): Length(m): 560 Width(m): Group size: Colour: black Construction: metal	Middle section leaning due to cattle.	Good	16-Jan-12	2 Years

Ref.	Type	Description	Measurements	Survey Notes	Overall Condition	Inspected	Inspect Period
DG65	Gate - 5 bar 'Double gate'	Double gate & enclosure for moving stock Inscription: "Authorised use only"	Height(m): Length(m): Width(m): Group size: Colour: black Construction: metal	2 of the posts are a bit loose.	Poor	16-Jan-12	1 Year
DG68	Gate - kissing	Double swing gates - a bit narrow. Inscription: "Please close the gate."	Height(m): Length(m): Width(m): Group size: Colour: Construction: wood	Bad rusting on hinges	Fair	16-Jan-12	-
W01	Water trough		Height(m): Length(m): 2 Width(m): Group size: Colour: black Construction: plastic	Badly poached area around the water	Good	16-Jan-12	1 Year