


Work Schedule of site furniture



Site name: Estate Land

Contact: Owner

Items: 0 Items requiring action: 0

Ref.	Type	Description	Measurements	Recommendations	Inspected	Priority / Timescale	Comments
DF34	Fence - post and rail 'pre-1980 model'	Between the two main pastures.	Height(m): Length(m): 70 Width(m): Group size: Colour: Construction: metal	A bit old - may need replacing if we get the extra cattle	16-Jan-12	16-Jan-14 (2 Years)	
DF37	Fence - post and rail	Along the main road.	Height(m): Length(m): 560 Width(m): Group size: Colour: black Construction: metal	nothing we can do!	16-Jan-12	16-Jan-14 (2 Years)	
DG65	Gate - 5 bar 'Double gate'	Double gate & enclosure for moving stock Inscription: "Authorised use only"	Height(m): Length(m): Width(m): Group size: Colour: black Construction: metal	repair/replace posts	16-Jan-12	16-Jan-15 (3 Years)	

Ref.	Type	Description	Measurements	Recommendations	Inspected	Priority / Timescale	Comments
DG68	Gate - kissing	Double swing gates - a bit narrow. Inscription: "Please close the gate."	Height(m): Length(m): Width(m): Group size: Colour: Construction: wood	Repaint on next maintenance cycle	16-Jan-12	16-Jan-15 (3 Years)	
W01	Water trough		Height(m): Length(m): 2 Width(m): Group size: Colour: black Construction: plastic	OK for now - but getting old. Will need to replace within 3 years	16-Jan-12	16-Jan-14 (2 Years)	